

**Golden Eagle
Park Dam
Construction
Photos**



Golden Eagle Park Dam

Construction Photos



DISK 10

JUNE 2000



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: June, 2000
- Location: upstream end of auxiliary outlet works
- Description: high groundwater exposed during excavation for new box culvert



- Date: June, 2000
- Location: upstream end of auxiliary outlet works
- Description: installing dewatering wells

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: June, 2000
- Location: northeast side of dam
- Description: stockpiled material from outlet works excavation



- Date: June, 2000
- Location: auxiliary outlet works
- Description: trench excavation for installation of the new box culvert

Golden Eagle Park Dam Construction of Improvements in 2000




- Date: June, 2000
- Location: upstream end of auxiliary outlet works
- Description: installing dewatering wells



- Date: June, 2000
- Location: auxiliary outlet works
- Description: material excavated from the trench for the new box culvert

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: June, 2000
- Location: north end of dam, looking south
- Description: stockpiled material shown on east side of dam



- Date: June, 2000
- Location: north end of dam
- Description: trenching for auxiliary outlet works

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: June, 2000
- Location: north end of dam
- Description: trenching for auxiliary outlet works



- Date: June, 2000
- Location: north end of dam looking south
- Description: stripped dam embankment

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: June, 2000
- Location: north end of dam
- Description: dewatering for auxiliary outlet works



- Date: June, 2000
- Location: north end of dam
- Description: trenching for auxiliary outlet works

DISK 11

JULY 2000



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: emergency spillway looking northeast
- Description: excavation



- Date: July 2000
- Location: emergency spillway looking northeast
- Description: excavation

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: sidewalk and bleachers at bottom of spillway
- Description: excavation exposing existing waterline to be protected in place



- Date: July 2000
- Location: crest of dam looking north
- Description: dam has been stripped and stockpiled material placed on downstream side behind the bleachers

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: auxiliary outlet works
- Description: trench excavation and subgrade at upstream end



- Date: July 2000
- Location: emergency spillway
- Description: excavation near downstream toe of spillway

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: auxiliary outlet works
- Description: construction of box culvert floor slab



- Date: July 2000
- Location: auxiliary outlet works
- Description: trench excavation and subgrade

Golden Eagle Park Dam Construction of Improvements in 2000




- Date: July 2000
- Location: auxiliary outlet works
- Description: construction of box culvert




- Date: July 2000
- Location: auxiliary outlet works
- Description: construction of box culvert floor slab

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: auxiliary outlet works
- Description: concrete pumper truck



- Date: July 2000
- Location: auxiliary outlet works
- Description: construction of box culvert floor slab

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: auxiliary outlet works
- Description: pouring concrete for box culvert floor slab



- Date: July 2000
- Location: auxiliary outlet works
- Description: pouring concrete for box culvert floor slab at upstream end

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: outlet structure on auxiliary outlet works box culvert
- Description: placing steel for apron



- Date: July 2000
- Location: outlet structure on auxiliary outlet works box culvert
- Description: placing steel for apron, cutting steel with saw

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: auxiliary outlet works
- Description: pouring concrete for outlet structure apron at downstream end



- Date: July 2000
- Location: auxiliary outlet works
- Description: construction of box culvert

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: auxiliary outlet works
- Description: pouring concrete for box culvert floor slab at upstream end

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: auxiliary outlet works, looking downstream
- Description: construction of box culvert floor slab



- Date: July 2000
- Location: auxiliary outlet works, upstream end
- Description: box culvert floor slab, wet cured

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: auxiliary outlet works
- Description: center floor slab of box culvert, just poured and sprayed with curing compound



- Date: July 2000
- Location: auxiliary outlet works
- Description: west end of box culvert, beginning forming for walls and deck slab


Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: auxiliary outlet works outlet structure
- Description: pouring and finishing apron



- Date: July 2000
- Location: auxiliary outlet works outlet structure
- Description: pouring and finishing apron



ID550-190




























DISK 12

JULY 2000



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: upstream end of auxiliary outlet works box culvert
- Description: beginning work on inlet structure



- Date: July 2000
- Location: upstream end of auxiliary outlet works box culvert
- Description: beginning work on inlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: center of auxiliary outlet works box culvert
- Description: applying curing compound



- Date: July 2000
- Location:
- Description:

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: downstream end of auxiliary outlet works box culvert
- Description: pouring concrete in walls of outlet structure




- Date: July 2000
- Location: downstream end of auxiliary outlet works box culvert
- Description: pouring concrete in walls of outlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: downstream end of auxiliary outlet works box culvert
- Description: preparing concrete cylinders for testing



- Date: July 2000
- Location: looking towards gymnasium
- Description: block wall in front of gymnasium is completed

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: looking towards gymnasium
- Description: block wall in front of gymnasium is completed



- Date: July 2000
- Location: downstream end of auxiliary outlet works box culvert
- Description: pumping concrete, preparing concrete cylinders for testing

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: upstream end of auxiliary box culvert
- Description: subgrade prepared for apron and cutoff



- Date: July 2000
- Location: existing inlet structure to principal outlet works
- Description: casing installed, prior to grouting

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: existing inlet structure to principal outlet works
- Description: casing installed, prior to grouting



- Date: July 2000
- Location: downstream end of auxiliary outlet works box culvert
- Description: pouring concrete in walls of outlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: principal outlet work outlet structure
- Description: plugged 60 inch pipe



- Date: July 2000
- Location: downstream end of auxiliary outlet works box culvert
- Description: pouring concrete in walls of outlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: emergency spillway looking southeast
- Description: new block wall



- Date: July 2000
- Location: emergency spillway looking southeast
- Description: new block wall

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: emergency spillway looking east
- Description: new block wall



- Date: July 2000
- Location: emergency spillway looking east
- Description: new block wall

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: alignment of the spillway floodwall
- Description: potholing for utility relocation

DISK 13

JULY 2000



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: floor slab poured, forming the walls and roof deck on upstream end



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: floor slab poured, forming the walls and roof deck on upstream end

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: floor slab poured, forming the walls and deck on downstream end



- Date: July 2000
- Location: crest of dam, north end
- Description: looking south along the dam crest

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: crest of dam, north end
- Description: looking south along the dam crest



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: constructing walls and deck slab in the center section

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: pouring walls and deck on the upstream end



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: pouring walls and deck on the downstream end

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: delivering concrete to the pumper



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: pouring concrete on the downstream end for walls and deck

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: spray curing compound being applied to upstream end



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: pouring concrete on the downstream end for walls and deck

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: pouring concrete on the downstream end for walls and deck




- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: forming the walls and deck for the center section

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: forming the walls for the outlet structure



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: forming the walls for the outlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: forming the center section and the outlet structure



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: forming the center section

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: upstream end after stripping forms



- Date: July 2000
- Location: spillway floodwall
- Description: electrical utility relocation near the floodwall, water has not been relocated yet

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: pumping concrete for the outlet structure



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: beginning work on the inlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: July 2000
- Location: Auxiliary Outlet Works
- Description: beginning work on the inlet structure



ID500-013

























DISK 14

AUGUST 2000



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: pouring walls and roof deck of center section



- Date: August 2000
- Location: auxiliary outlet works
- Description: pouring walls of outlet structure

Golden Eagle Park Dam Construction of Improvements in 2000

- Date: August 2000
- Location: auxiliary outlet structure
- Description: pouring walls of outlet structure



- Date: August 2000
- Location: auxiliary outlet structure
- Description: spray curing compound applied to center section of box roof deck



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: construction of the box culvert




- Date: August 2000
- Location: principal outlet works
- Description: installation of the 24 inch casing inside the 60 inch pipe

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: principal outlet works
- Description: installation of the 24 inch casing inside the 60 inch pipe



- Date: August 2000
- Location: principal outlet works
- Description: installation of the 24 inch casing inside the 60 inch pipe

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: pouring concrete in the outlet structure wing walls



- Date: August 2000
- Location: principal outlet works
- Description: 60 inch pipe plug at downstream end

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: pouring concrete in the outlet structure wing walls



- Date: August 2000
- Location: auxiliary outlet works
- Description: pouring concrete in the outlet structure wing walls

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: emergency spillway
- Description: masonry retaining wall completed



- Date: August 2000
- Location: emergency spillway
- Description: excavation of emergency spillway

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: emergency spillway
- Description: masonry retaining wall



- Date: August 2000
- Location: emergency spillway
- Description: masonry retaining wall

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: upstream toe of dam (Cloudburst Wash)
- Description: placement of dam embankment and construction of toe trench for riprap, irrigation lines exposed and relocated



- Date: August 2000
- Location: auxiliary outlet works
- Description: constructing inlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: constructing inlet structure, beginning backfill upstream of the core



- Date: August 2000
- Location: auxiliary outlet works
- Description: forms stripped, beginning backfill upstream of the core

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: stripping forms, excavating downstream channel



- Date: August 2000
- Location: upstream of auxiliary outlet works
- Description: pumping water due to rain and broken waterline

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: backfilling box culvert, beginning structural backfill around wingwalls




- Date: August 2000
- Location: auxiliary outlet works
- Description: stripping forms on inlet structure, placing concrete at principal inlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: dam embankment looking south
- Description: placing riprap at toe of dam



ID823-011



























DISK 15

AUGUST 2000



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: upstream dam embankment
- Description: repairing broken irrigation line



- Date: August 2000
- Location: upstream dam embankment
- Description: placing riprap

Golden Eagle Park Dam Construction of Improvements in 2000




- Date: August 2000
- Location: auxiliary outlet works
- Description: backfilling over box culvert



- Date: August 2000
- Location: upstream dam embankment
- Description: placing riprap

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: outlet structure



- Date: August 2000
- Location: auxiliary outlet works
- Description: outlet structure filled with sediment from recent rain

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: principal outlet works inlet structure
- Description: forming for the new headwall and apron



- Date: August 2000
- Location: upstream dam embankment
- Description: placing riprap

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: upstream dam embankment
- Description: placing riprap



- Date: August 2000
- Location: auxiliary outlet works
- Description: inlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: upstream dam embankment
- Description: placing riprap



- Date: August 2000
- Location: upstream dam embankment
- Description: placing riprap and backfilling

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: emergency spillway
- Description: 24" and 60" concrete pipe for installation in the principal outlet works



- Date: August 2000
- Location: emergency spillway
- Description: 24" and 60" concrete pipe for installation in the principal outlet works

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works inlet structure
- Description: riprap placed around structure



- Date: August 2000
- Location: principal outlet works inlet structure
- Description: forming for the inlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: principal outlet works
- Description: installing pipe and connection to the new structure



- Date: August 2000
- Location: auxiliary outlet works
- Description: backfilling over the box culvert, placing sand diaphragm in trench

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: outlet structure and channel partially lined with riprap



- Date: August 2000
- Location: spillway floodwall
- Description: trenching and forming for wall footing

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: spillway floodwall
- Description: excavation through caliche for wall footing



- Date: August 2000
- Location: auxiliary outlet works
- Description: excavating outlet channel and lining with riprap

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: principal outlet works
- Description: forming for inlet structure



- Date: August 2000
- Location: auxiliary outlet works
- Description: excavation of outlet channel and lining with riprap


Golden Eagle Park Dam Construction of Improvements in 2000




- Date: August 2000
- Location: spillway floodwall
- Description: footing and rebar for low wall



ID508-938



























DISK 16

AUGUST 2000



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: spillway floodwall
- Description: footing and rebar for short wall



- Date: August 2000
- Location: spillway floodwall
- Description: footing and rebar for tall wall

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: spillway floodwall
- Description: footer and steel for tall wall



- Date: August 2000
- Location: auxiliary outlet works
- Description: outlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: outlet structure




- Date: August 2000
- Location: auxiliary and principal outlet works
- Description: backfilling over auxiliary outlet works box culvert, principal inlet structure forms stripped

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: spillway floodwall
- Description: pouring concrete using crane and bucket



- Date: August 2000
- Location: auxiliary outlet works
- Description: outlet structure and channel

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: grizzly used to screen onsite soil for replacement in the impervious zone



- Date: August 2000
- Location: downstream side of dam looking south
- Description: stockpiled material mostly gone and placed on upstream face and top of dam

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: left abutment of dam
- Description: grading haul road up the abutment to the church property



- Date: August 2000
- Location: left abutment looking south
- Description: auxiliary outlet works trench backfilled and upstream embankment being raised

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: left abutment looking south
- Description: auxiliary outlet works trench backfilled and upstream embankment being raised




- Date: August 2000
- Location: left abutment looking south
- Description: auxiliary outlet works trench backfilled and upstream embankment being raised

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: left abutment looking south
- Description: auxiliary outlet works trench backfilled and upstream embankment being raised



- Date: August 2000
- Location: spillway floodwall looking south
- Description: footing and rebar for tall floodwall

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: spillway floodwall looking south
- Description: footing and rebar for tall floodwall, pouring concrete stem for short wall in the distance



- Date: August 2000
- Location: emergency spillway looking north
- Description: excavating to subgrade for gabions

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: auxiliary outlet works
- Description: outlet structure and channel looking east



- Date: August 2000
- Location: upstream side of dam looking east toward outlet works
- Description: inlet structures completed, riprap placed and embankment is being raised

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: upstream side of dam looking east toward outlet works
- Description: inlet structures completed, riprap placed and embankment is being raised



- Date: August 2000
- Location: upstream side of dam looking east toward outlet works
- Description: inlet structures completed, riprap placed and embankment is being raised


Golden Eagle Park Dam Construction of Improvements in 2000



- Date: August 2000
- Location: principal outlet works
- Description: inlet structures completed, riprap placed and embankment is being raised



- Date: August 2000
- Location: upstream side of dam looking south along toe of embankment
- Description: inlet structures completed, riprap placed and embankment is being raised



ID276-092





















Kodak

DuraLife
PAPER







DISK 17

SEPTEMBER, OCTOBER 2000



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: September 2000
- Location: right end of spillway
- Description: south end of floodwall



- Date: September 2000
- Location: southwest of spillway
- Description: staging area and dam embankment in background

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: September 2000
- Location: emergency spillway
- Description: excavation for gabions, spillway cutoff wall



- Date: September 2000
- Location: emergency spillway
- Description: excavation for gabions, spillway cutoff wall

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: September 2000
- Location: north end of dam looking south
- Description: dam embankment partially raised



- Date: September 2000
- Location: intersection of Palisades and Shea Blvd
- Description: excavating and screening proposed borrow material for impervious fill

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: September 2000
- Location: intersection of Palisades and Shea Blvd
- Description: excavating proposed borrow material for impervious fill




- Date: September 2000
- Location: south end of spillway
- Description: spillway floodwall completed and partially backfilled

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: September 2000
- Location: emergency spillway, looking east
- Description: spillway floodwall completed and partially backfilled



- Date: September 2000
- Location: emergency spillway, looking north
- Description: gabions delivered to site

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: September 2000
- Location: emergency spillway looking north
- Description: work beginning on gabions



- Date: September 2000
- Location: emergency spillway looking northeast
- Description: work beginning on gabions

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: September 2000
- Location: toe of emergency spillway
- Description: installing gabions and anchor posts



- Date: September 2000
- Location: north end of dam
- Description: principal outlet works inlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: October 2000
- Location: north end of dam
- Description: principal outlet works inlet structure



- Date: October 2000
- Location: north end of dam
- Description: principal outlet works inlet structure

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: October 2000
- Location: north end of dam
- Description: auxiliary outlet works inlet structure




- Date: October 2000
- Location: north end of dam, looking south
- Description: dam embankment partially raised

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: October 2000
- Location: auxiliary outlet works, looking east
- Description: channel grading partially completed



- Date: October 2000
- Location: near floodwall
- Description: small sheepfoot compactor used for compaction around structures

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: October 2000
- Location: emergency spillway
- Description: desert varnish stain sample applied to the floodwall



13 OCT 00
4/3/2


























DISK 18

NOVEMBER 2000



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Auxiliary Spillway
- Description: Inlet structure, embankment partially raised



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions



- Date: November 2000
- Location: dam embankment looking south
- Description: embankment partially raised

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions and backfilling



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions and backfilling

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions and backfilling



- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions

Golden Eagle Park Dam Construction of Improvements in 2000




- Date: November 2000
- Location: Emergency Spillway
- Description: Installing gabions and backfilling
























DISK 19

NOVEMBER, DECEMBER 2000



Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency spillway looking north
- Description: Grading upstream of the spillway cutoff wall



- Date: November 2000
- Location: Emergency Spillway looking northwest
- Description: gabions, fence and wall finished on spillway

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway looking northwest
- Description: gabions, fence and wall finished on spillway, working on right dam abutment protection



- Date: November 2000
- Location: Emergency Spillway looking southeast
- Description: floodwall and grading finished

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway looking northwest
- Description: placing fuseplug over gabions



- Date: November 2000
- Location: Emergency Spillway looking southwest
- Description: placing fuseplug over gabions

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Emergency Spillway looking south
- Description: placing fuseplug over gabions



- Date: November 2000
- Location: Dam embankment looking south
- Description: placing imported impervious fill

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Dam embankment looking north
- Description: trimming dam embankment with Gradall



- Date: November 2000
- Location: Dam embankment looking northeast
- Description: trimming dam embankment with Gradall

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: November 2000
- Location: Dam embankment looking south
- Description: placing imported impervious fill



- Date: November 2000
- Location: Dam embankment looking south
- Description: placing imported impervious fill

Golden Eagle Park Dam Construction of Improvements in 2000




- Date: November 2000
- Location: Auxiliary outlet works looking southwest
- Description: trimming embankment with the Gradall



- Date: November 2000
- Location: Dam embankment looking northwest
- Description: trimming dam embankment with Gradall

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: December 2000
- Location: Right abutment looking southwest
- Description: Spillway floodwall finished



- Date: December 2000
- Location: Right abutment looking northeast
- Description: Spillway floodwall finished

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: December 2000
- Location: Emergency spillway looking northeast
- Description: Placing fuseplug, gabions and constructing sidewalk



- Date: December 2000
- Location: Emergency spillway looking northwest
- Description: Constructing sidewalk

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: December 2000
- Location: Emergency spillway looking north
- Description: Placing fuseplug and constructing gabions



- Date: December 2000
- Location: Emergency spillway looking north
- Description: Hydroseeding the dam and cleaning up the spillway

Golden Eagle Park Dam Construction of Improvements in 2000



- Date: December 2000
- Location: Emergency spillway looking north
- Description: Hydroseeding the dam and spillway



- Date: December 2000
- Location: Emergency spillway looking north
- Description: Finished construction at the spillway



21 DEC 00 43/2

























DISK 20

DECEMBER, JANUARY 2000

