

1-15-93



LOOKING SOUTH FROM BETHANY HOME ROAD

1-15-93

Property of
Flood Control District of MC Library
Please Return to
2801 W. Durango
Phoenix, AZ 85009



LOOKING SOUTH OF GLENDALE AVENUE BRIDGE


1-15-93

2



LOOKING NORTH OF GLENDALE AVENUE BRIDGE

1-15-93 3




LOOKING NORTH OF GLENDALE AVENUE BRIDGE

1-15-93 4



NORTH WEST CORNER OF GLENDALE AVENUE BRIDGE

1-15-93 5



LOOKING SOUTH EAST OF NORTHERN AVENUE BRIDGE

1-15-93 6



5.0.
LOOKING WEST FROM SOUTH SIDE OF NORTHERN AVENUE BRIDGE

1-15-93 7



LOOKING WEST FROM SOUTH SIDE OF NORTHERN AVENUE BRIDGE

1-15-93 8



LOOKING WEST FROM THE NORTH SIDE OF NORTHERN AVENUE BRIDGE

1-15-93 9



LOOKING NORTH AT SRP'S POWER TRANSMISSION TOWERS

1-15-93 10



LOOKING NORTH AT SRP'S POWER TRANSMISSION TOWERS

1-15-93 11



SUN CITY OUTLET

1-15-93 12



SUN CITY OUTLET

1-15-93 13



SOUTH WEST CORNER OF OLIVE AVENUE BRIDGE

1-15-93 14



LOOKING NORTH FROM OLIVE AVENUE

1-15-93 15



LOOKING EAST,
SOUTH OF OLIVE SHOWING INVERT PROTECTION (WEST HALF)

4-21-93



LOOKING NORTH
SOUTH OF OLIVE SHOWING INVERT PROTECTION (WEST HALF)

4-21-93



DIKE FOR DIVERTING FLOWS NORTH OF OLIVE

4-21-93



NORTH OF OLIVE SHOWING INVERT PROTECTION (WEST HALF)

4-21-93



LOOKING NORTH
SOUTH OF OLIVE SHOWING INVERT PROTECTION (WEST HALF)

4-21-93



LOOKING WEST
SOUTH OF OLIVE SHOWING INVERT PROTECTION (WEST HALF)
AND ABUTMENT PROTECTION

4-21-93



LOOKING WEST SHOWING THE INLET BOX,
CHANNEL EXCAVATION AND APRON FOR THE OUTLET BOX
(READY FOR FLEX BLOCK PLACEMENT)

4-21-93



LOOKING WEST SHOWING THE EXCAVATION FOR PLACEMENT
OF FLEXBLOCK FOR THE SUN CITY CHANNEL OUTLET

4-21-93



LOOKING EAST SHOWING THE SUN CITY CHANNEL BOX OUTLET
AND NEPDES WHICH WAS NOT EXPECTED

4-21-93



LOOKING NORTH SHOWING NEPDES WHICH WAS NOT EXPECTED

4-21-93



LOOKING SOUTH SHOWING NEPDES WHICH WAS NOT EXPECTED

4-21-93



LOOKING SOUTH FROM OLIVE SHOWING BANK AND TOE DOWN
EXCAVATION AT SUN CITY CHANNEL OUTLET

4-21-93



LOOKING EAST SHOWING THE SUN CITY CHANNEL BOX OUTLET
AND NEPDES WHICH WAS NOT EXPECTED

4-21-93



LOOKING NORTH SHOWING NEPDES WHICH WAS NOT EXPECTED

4-21-93



LOOKING NORTH FROM NORTHERN.
CHANNEL EXCAVATION BY SRP POWER LINE

4-21-93



LOOKING SOUTH FROM NORTHERN
SHOWING WEST SIDE OF CHANNEL EXCAVATION

4-21-93



SHOWING THE STOCKPILE OF MATERIAL FOR SOIL CEMENT
ON THE 20 ACRE MITIGATION SITE NORTH OF GLENDALE

4-21-93



LOOKING NORTH FROM GLENDALE AVENUE BRIDGE

4-21-93



LOOKING SOUTH FROM GLENDALE AVENUE BRIDGE


4-21-93



1/4 MILE NORTH OF OLIVE NEAR GRADE CONTROL

STRUCTURE LOOKING NORTH

6-10-93



1/4 MILE NORTH OF OLIVE NEAR GRADE CONTROL

STRUCTURE LOOKING SOUTH

6-10-93



LOOKING NORTH FROM OLIVE AVENUE BRIDGE

6-10-93



NORTH SIDE OF OLIVE LOOKING EAST

6-10-93



SOUTH OF OLIVE LOOKING EAST

6-10-93




LOOKING SOUTH FROM OLIVE

6-10-93



SUNCITY CHANNEL, HEADWALL SHOWING
GRADING & NPDES LOOKING NORTH EAST

6-10-93



SUN CITY CHANNEL, FLEX BLOCK LOOKING EAST

6-10-93




SOUTH OF OLIVE ON EAST BANK LOOKING SOUTH

6-10-93



SOUTH OF OLIVE ON EAST BANK LOOKING NORTH

6-10-93



SOUTH OF OLIVE LOOKING SOUTH

6-10-93



SOUTH OF OLIVE ON EAST BANK LOOKING SOUTH

6-10-93




NORTH OF NORTHERN LOOKING NORTH WEST

6-10-93



AT NORTHERN LOOKING NORTH EAST

6-10-93



AT NORTHERN LOOKING NORTH

6-10-93



AT NORTHERN LOOKING NORTH

6-10-93



SOIL CEMENT PLANT AT NORTHERN

6-10-93



SOIL CEMENT PLANT AT NORTHERN

6-10-93



AT GLENDALE LOOKING NORTH

6-10-93



AT GLENDALE LOOKING NORTH

6-10-93



GLENDALE FILL SITE LOOKING NORTH EAST

6-10-93



AT GLENDALE NORTH WEST CORNER

6-10-93



AT GLENDALE LOOKING SOUTH

6-10-93