

FLOOD PHOTOS FOR 1978

CONTACT SHEET # 1 - 120 Photos

Property of
Flood Control District of MC Library
Please Return to
2301 W. Durango
Phoenix, AZ 85009






PHOTO CAPTION SHEET

Contact Sheet #1

Number: #1 Date 3-3-78
 Subject: Flood Damage - Indian Bend Wash
 Description: View of bike path crossing
of IBW between Princess Road and McKellips
Road looking northeasterly from south
dike.

Number: #5 Date 3-3-78
 Subject: Salt River - Flooding
 Description: View of north approach to
Hayden Road bridge.

Property of
 Flood Control District of MC Library
 Please Return to
 2801 W. Durango
 Phoenix, AZ 85009

Number: #2 Date 3-3-78
 Subject: Wet areas in front of Cadena and
businesses adjacent thereto
 Description: _____
View looking from south to north of wet
areas behind dike between Rogers and
Cadena.

Number: #6 Date 3-3-78
 Subject: Salt River - Flooding
 Description: View of APS bracing a power
pole on the south end of Scottsdale Road
bridge.

Number: #3 Date 3-3-78
 Subject: Indian Bend Wash
 Description: View of bike path crossing
constructed by City of Tempe looking
north from Princess Road bridge.

Number: #7 Date 3-3-78
 Subject: Salt River - Flooding
 Description: View of water flow immediately
downstream of Scottsdale Road bridge.

Number: #4 Date 3-3-78
 Subject: Indian Bend Wash
 Description: View of Nina Stake Yard
looking easterly from Princess Road.

Number: #8 Date 3-3-78
 Subject: Salt River - Flooding
 Description: View of damage to street
paving prior to reaching south approach
to Scottsdale Road bridge. Note water
flow south end of bridge down thru ASU
parking lot.

CONTACT SHEET #1 - Negatives

CONTACT SHEET #2 - 120 Photos

① 9




② 10




③ 11



④ 12



⑤ 13



⑥ 14



⑦ 15



⑧ 16



CONTACT SHEET #2 - Negatives

PHOTO CAPTION SHEET

Contact Sheet #2

<p>Number: <u>#1 (9)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Salt River - Flooding</u></p> <p>Description: <u>View of north approach to Hayden Road bridge.</u></p>	<p>Number: <u>#5 (13)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Salt River - Flooding</u></p> <p>Description: <u>View of Mill Avenue bridges as seen from south bank and immediately downstream.</u></p>
<p>Number: <u>#2 (10)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Salt River - Flooding</u></p> <p>Description: <u>View of flow under Hayden Road bridge and cutout south approach as seen from south bank downstream.</u></p>	<p>Number: <u>#6 (14)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Salt River - Flooding</u></p> <p>Description: <u>View of Mill Avenue bridge (one of three river crossings) as seen from deck of old condemned bridge.</u></p>
<p>Number: <u>#3 (11)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Salt River - Flooding</u></p> <p>Description: <u>Existing Mill Avenue bridge as reviewed from east end of old condemned bridge downstream.</u></p>	<p>Number: <u>#7 (15)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Salt River - Flooding</u></p> <p>Description: <u>View of water level immediately upstream of Scottsdale Road bridge.</u></p>
<p>Number: <u>#4 (12)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Salt River - Flooding</u></p> <p>Description: <u>Existing Mill Avenue bridges as viewed from south bank downstream rail-road bridge.</u></p>	<p>Number: <u>#8 (16)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Salt River - Flooding</u></p> <p>Description: <u>View of railroad bridge as seen from south bank and downstream.</u></p>

CONTACT SHEET # 3 - Negatives

CONTACT SHEET #3 - 120 Photos




PHOTO CAPTION SHEET

Contact Sheet #3

<p>Number: #1 (17) Date 3-3-78</p> <p>Subject: Salt River - Flooding</p> <p>Description: View of Salt River between Mill Avenue and Scottsdale Road bridge as seen from Mill Avenue bridge.</p>	<p>Number: #5 (21) Date 3-3-78</p> <p>Subject: Salt River - Flooding</p> <p>Description: View of west bound Mill Avenue as seen from east bank at street level.</p>
<p>Number: #2 (18) Date 3-3-78</p> <p>Subject: Salt River - Flooding</p> <p>Description: View of channel cut around south appr. to Hayden Road bridge immediately upstream of Hayden Road. Front-end loader parked for stand by use by private party.</p>	<p>Number: #6 (22) Date 3-3-78</p> <p>Subject: Salt River - Flooding</p> <p>Description: View of flow through Hayden Road bridge as seen from south bank downstream.</p>
<p>Number: #3 (19) Date 3-3-78</p> <p>Subject: Salt River - Flooding</p> <p>Description: View of washed out dike upstream of Scottsdale Road and ASU parking lot as seen from east shoulder of Scottsdale Road.</p>	<p>Number: #7 (23) Date 3-3-78</p> <p>Subject: Salt River - Flooding</p> <p>Description: View of flow through washed out south approach to Hayden Road bridge as seen from south bank and downstream.</p>
<p>Number: #4 (20) Date 3-3-78</p> <p>Subject: Salt River - Flooding</p> <p>Description: View of south approach to Scottsdale Road bridge showing channel in foreground of flow down through ASU parking lot.</p>	<p>Number: _____ Date _____</p> <p>Subject: _____</p> <p>Description: _____</p>

CONTACT SHEET #4 - 120 Photos



CONTACT SHEET #4 - Negatives

PHOTO CAPTION SHEET

Contact Sheet #4

Number: #1 (24) Date 3-3-78

Subject: Indian Bend Wash - Flooding

Description: View of intersection of Indian School and Hayden Roads.

Number: #5 (28) Date 3-3-78

Subject: Indian Bend Wash - Flooding

Description: View of erosion and lake water - SW corner of Indian School and Hayden Roads.

Number: #2 (25) Date 3-3-78

Subject: Indian Bend Wash - Flooding

Description: View of box culvert street crossing at Indian School and Hayden Roads.

Number: #6 (29) Date 3-3-78

Subject: Indian Bend Wash - Flooding

Description: View of water erosion - SW corner of Indian School and Hayden Roads.

#2 + #4

Number: #3 (26) Date 3-3-78

Subject: Indian Bend Wash - Flooding

Description: View of erosion downstream of Indian School and Hayden Roads.

Number: #7 (30) Date 3-3-78

Subject: Indian Bend Wash - Flooding

Description: View of Chapparal and Hayden Road intersection looking from South to North.

Number: #4 (27) Date 3-3-78

Subject: Indian Bend Wash - Flooding

Description: View of erosion downstream of Indian School and Hayden Roads.

Number: #8 (31) Date 3-3-78

Subject: Indian Bend Wash - Flooding

Description: View of Cambelback and Hayden Road intersection looking northeasterly.

PHOTO CAPTION SHEET

Contact Sheet #4

<p>Number: <u>#1 (24)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Indian Bend Wash - Flooding</u></p> <p>Description: <u>View of intersection of</u> <u>Indian School and Hayden Roads.</u></p>	<p>Number: <u>#5 (28)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Indian Bend Wash - Flooding</u></p> <p>Description: <u>View of erosion and lake</u> <u>water - SW corner of Indian School and</u> <u>Hayden Roads.</u></p>
<p>Number: <u>#2 (25)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Indian Bend Wash - Flooding</u></p> <p>Description: <u>View of box culvert street</u> <u>crossing at Indian School and Hayden</u> <u>Roads.</u></p>	<p>Number: <u>#6 (29)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Indian Bend Wash - Flooding</u></p> <p>Description: <u>View of water erosion -</u> <u>SW corner of Indian School and Hayden</u> <u>Roads.</u></p>
<p>Number: <u>#3 (26)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Indian Bend Wash - Flooding</u></p> <p>Description: <u>View of erosion downstream</u> <u>of Indian School and Hayden Roads.</u></p>	<p>Number: <u>#7 (30)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Indian Bend Wash - Flooding</u></p> <p>Description: <u>View of Chapparal and</u> <u>Hayden Road intersection looking from</u> <u>South to North.</u></p>
<p>Number: <u>#4 (27)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Indian Bend Wash - Flooding</u></p> <p>Description: <u>View of erosion downstream</u> <u>of Indian School and Hayden Roads.</u></p>	<p>Number: <u>#8 (31)</u> Date <u>3-3-78</u></p> <p>Subject: <u>Indian Bend Wash - Flooding</u></p> <p>Description: <u>View of Cambelback and</u> <u>Hayden Road intersection looking</u> <u>northeasterly.</u></p>

CONTACT SHEET #5 - 120 PHOTOS

D



CONTACT SHEET #5 - Negatives

PHOTO CAPTION SHEET

Contact Sheet #5

Number: #1 (32) Date 3-15-78
 Subject: Salt River - Flooding
 Description: View of 19th Avenue bridge
structure as seen from south bank
upstream.

Number: #5 (36) Date 3-15-78
 Subject: Salt River - Flooding
 Description: Close-up view of upstream
side of 19th Avenue bridge structure.

Number: #2 (33) Date 3-15-78
 Subject: Salt River - Flooding
 Description: View of 19th Avenue bridge
structure as seen from south bank and
upstream.

Number: #6 (37) Date 3-15-78
 Subject: Salt River - Flooding
 Description: Closeup view of south end
of 19th Avenue bridge structure.

Number: #3 (34) Date 3-15-78
 Subject: Salt River - Flooding
 Description: View of 19th Avenue bridge
and stored concrete masonry units on
south bank as seen from south bank
upstream.

Number: #7 (38) Date 3-15-78
 Subject: Salt River - Flooding
 Description: View of north bank in
vicinity of north approach area to
19th Avenue bridge.

Number: #4 (35) Date 3-15-78
 Subject: Salt River - Flooding
 Description: View of 19th Avenue bridge
structure and approach area along north
bank.

Number: _____ Date _____
 Subject: _____
 Description: _____

CONTACT SHEET #6 - 120 PHOTOS




→10



→11

→12



→8

→6

→7

→3

→4

→5

"Film Roll Problems"

PHOTO CAPTION SHEET

Contact Sheet #6

Number: #1 (3a) Date 3-15-78
Subject: Salt River - Flooding
Description: View of broken pipe lines
in road bed at washed out north approach
to 19th Avenue bridge crossing as seen
from north bank and downstream.

Number: _____ Date _____
Subject: _____
Description: _____

Number: #2 (4a) Date 3-15-78
Subject: Salt River - Flooding
Description: View of concrete masonry unit
storage on the south bank of river
immediately upstream of south bridge
approach as seen from north bank.

Number: _____ Date _____
Subject: _____
Description: _____

Number: #3 (4b) Date 3-15-78
Subject: Salt River - Flooding
Description: View of 19th Avenue bridge
structure as seen from the north bank
and approach area.

Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

CONTACT SHEET #6 - Negatives

CONTACT SHEET # 7 ^{35mm} - ~~120~~ PHOTOS

SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062



→16

→16A

→17

→17A

→18

→18A

→19

→19A

→20

→20A

SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK



→11

→11A

→12

→12A

→13

→13A

→14

→14A

→15

→15A

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SA



→5

→5A

→6

→6A

→7

→7A

→8

→8A

→9

→9A


→10

→10A

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062



→0A

→1

→1A

→2

→2A

→3

→3A

→4

0

9

7

CONTACT SHEET #7 - Negatives

PHOTO CAPTION SHEET

Number: 1 (42) Date 3-6-78
 Subject: Residence in Salt-Gila Flood-plain.
 Description: Residence located south of Southern Avenue, on east side of 115th Avenue. Highwater mark shows on house.

Number: 2 (43) Date 3-6-78
 Subject: Residence in salt-Gila flood-plain.
 Description: Residence located south of Southern Ave. - 1/2 mile and west of 115th Ave. Residence faces east.

Salt-Gila
Flooding
1978

Number: 3 (44) Date 3-6-78
 Subject: Looking south on 115th Ave.
 Description: Salt-Gila
Mobile home cracked in half. Tanker truck left side of photo and small white car nose down off right side of road.

Number: 4 (45) Date 3-6-78
 Subject: Looking Southeast from 115th Ave. & Salt-Gila
 Description: Ave. & Salt-Gila
Mobile home and vehicle damage in the vicinity of at east side of 115th Ave.

Number: 5 (46) Date 3-6-78
 Subject: Gila River
 Description: Taken from Southern Ave due southwest of 115th Ave looking at PIR. Mobile home and livestock losses.

Number: 6 (47) Date 3-6-78
 Subject: Gila River flooding in Holly acres.
 Description: Residence with high-water mark, just south of Southern Ave. and east of 123rd Ave.

Number: 7 (48) Date 3-6-78
 Subject: Gila River flooding in Holly acres.
 Description: Photo of residences in Holly Acres looking east off of 123rd Avenue south of Southern.

Number: 8 (49) Date 3-6-78
 Subject: Gila River flooding of Holly Acres.
 Description: Looking south on 123rd Avenue-east side. Obstruction caused by fencing evident.

PHOTO CAPTION SHEET

Number: 1 (42) Date 3-6-78
 Subject: Residence in Salt-Gila Flood-plain.
 Description: Residence located south of Southern Avenue, on east side of 115th Avenue. Highwater mark shows on house.

Number: 2 (43) Date 3-6-78
 Subject: Residence in salt-Gila flood-plain.
 Description: Residence located south of Southern Ave. - 1/2 mile and west of 115th Ave. Residence faces east.

Number: 3 (44) Date 3-6-78
 Subject: Looking south on 115th Ave. &
 Description: Salt-Gila
Mobile home cracked in half. Tanker truck left side of photo and small white car nose down off right side of road.

Number: 4 (45) Date 3-6-78
 Subject: Looking Southeast from 115th
 Description: Ave. & Salt-Gila
Mobile home and vehicle damage in the vicinity of at east side of 115th Ave.

Number: 5 (46) Date 3-6-78
 Subject: Gila River
 Description: Taken from Southern Ave due southwest of 115th Ave looking at PIR. Mobile home and livestock losses.

Number: 6 (47) Date 3-6-78
 Subject: Gila River flooding in Holly acres.
 Description: Residence with high-water mark, just south of Southern Ave. and east of 123rd Ave.

Number: 7 (48) Date 3-6-78
 Subject: Gila River flooding in Holly acres.
 Description: Photo of residences in Holly Acres looking east off of 123rd Avenue south of Southern.

Number: 8 (49) Date 3-6-78
 Subject: Gila River flooding of Holly Acres.
 Description: Looking south on 123rd Avenue-east side. Obstruction caused by fencing evident.

PHOTO CAPTION SHEET

Number: 9 (50) Date 3-6-78

Subject: Indian School Rd. Bridge & Agua Fria.

Description: Upstream side of bridge looking west. Note high water mark.

Number: 10 (51) Date 3-6-78

Subject: Olive Avenue Bridge & New River

Description: Upstream side of bridge looking west. Highwater mark on piers.

Number: 11 (52) Date 3-6-78

Subject: Agua Fria and Grand Avenue.

Description: Looking west on upstream side of R.R. bridge. Milwaukee Brewers-Sun City training facility centers of photo.

Number: 12 (53) Date 3-6-78

Subject: Agua Fria and AT & SF Railroad Bridge.

Description: Upstream side at bridge looking west. Highwater mark piers.

Number: 13 (54) Date 3-6-78

Subject: Agua Fria just upstream of Grand Ave.

Description: Looking upstream at Brewers-Sun City baseball training facility. Note highwater mark on building and center field fencing standing.

Number: 14 (55) Date --

Subject: Mis-flash

Description: -----

Number: 15 (56) Date 3-6-78

Subject: Double Exposure

Description: -----

Number: 16 (57) Date 3-7-78

Subject: Gila River flooding in Holly Acres. (123 rd ave)

Description: Decker residence showing highwater mark. Permit was issued by Board of Supervisors as a variance to Flood-plain regulations.

PHOTO CAPTION SHEET

Number: 17 (58) Date 3-7-78
Subject: Gila River flooding vicinity
Description: 121st Ave.

Marcom residence and Property flood-
ing located just east of Holly Acres.
Floodplain variance issued by Board
of Supervisors.

Number: 19 (60) Date 3-7-78
Subject: Gila River flooding vicinity
Description: of 119th Avenue.

Clemit residence showing highwater
mark. South of Southern north 660
feet on 119th Avenue.

Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

Number: 18 (59) Date 3-7-78
Subject: Gila River flooding vicinity
Description: of 119th Avenue.

Clemit property flooding. Variance
to floodplain regulation was issued
for this property by Board of Super-
visors.

Number: 20 (61) Date 3-7-78
Subject: Gila River flooding vicinity
Description: 125th Avenue.

Garcia residence subject to shallow
floodings- protected by diversion of
flows by irrigation ditch on east
property line.

Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

Number: 1 (62) Date 3/3/78 (10:30 am)

Subject: Indian School Road Bridge

Description: Downstream looking
northwest

Number: 2 (63) Date 3/3/78 (10:30am)

Subject: _____

Description: From Indian School Road
Bridge looking downstream.

Number: 3 (64) Date 3/3/78 (10:30a.m.)

Subject: Panoramic view from Indian School
Road Bridge

Description: The sand and gravel company on
west side of river is working on a dike to
prevent water from entering their pit.

Number: 4 (65) Date 3/3/78

Subject: _____

Description: From Indian School Bridge
looking downstream at sand and gravel
company on east side of river.

Number: 5 (66) Date 3/3/78 (10:30 am)

Subject: _____

Description: From north side of Indian School
Road at east end of bridge looking east. A
large volume of water approaches the road
embankment east of the bridge and flows
west along the embankment. Highway may wish
to train the water to the bridge to avoid
damage in a larger flood.

Number: 6 (67) Date 3/3/78 (10:30am)

Subject: Same water

Description: looking west upstream of
Indian School Road bridge.

Number: 7 (68) Date 3/3/78 (3 to 3:30)

Subject: Cave Creek Dam

Description: _____

Number: 8 (69) Date 3/3 (3 to 3:30 pm)

Subject: Cave Creek Dam

Description: _____

Number: 9 (70) Date 3/3 (3 to 3:30 pm)

Subject: Cave Creek Dam

Description: _____

Number: 10 (71) Date 3/3 (3 to 3:30 pm)

Subject: Cave Creek Dam =

Description: _____

Number: 11 (72) Date 3/3 (3 to 3:30 pm)

Subject: Cave Creek Dam

Description: _____

Number: 12 (73) Date 3/3 (3 to 3:30 pm)

Subject: Cave Creek Dam

Description: _____

Number: 13 (74) Date 3/5 (8 am)

Subject: Cave Creek Dam

Description: _____

Number: 14 (75) Date 3/5 (8 am)

Subject: Cave Creek Dam

Description: _____

Number: 15 (76) Date 3/5 (8 am)

Subject: Cave Creek Dam

Description: _____

Number: 16 (77) Date 3/5 (9 am)

Subject: On Salt or Gila Rivers

Description: _____

● CONTACT SHEET #8

KODAK SAFETY FILM 5062



→ 15A

KODAK SAFETY FILM 5062



→ 16

→ 16A

→ 17



→ 17A

→ 18

KODAK SAFETY FILM 5062



→ 18A

→ 19

KODAK SAFETY FILM 5062



→ 19A

→ 20



→ 20A

KODAK SAFETY FILM 5062



→ 10A

→ 11

KODAK SAFETY FILM 5062



→ 11A

→ 12



→ 12A

→ 13

KODAK SAFETY FILM 5062



→ 13A

→ 14

KODAK SAFETY FILM 5062



→ 14A

→ 15

KODAK SAFETY FILM 5062



→ 5A

→ 6

KODAK SAFETY FILM 5062



→ 6A

→ 7

KODAK SAFETY FILM 5062



→ 7A

→ 8

KODAK SAFETY FILM 5062



→ 8A

→ 9



→ 9A

→ 10

KODAK SAFETY FILM 5062



→ 0A

→ 1

KODAK SAFETY FILM 5062



→ 1A

→ 2

KODAK SAFETY FILM 5062



→ 2A

→ 3

KODAK S



→ 3A

→ 4



→ 4

1 4 2

→ 5

Number: 17 (78) Date 3/5 (9:30 am)

Subject: Gillespie Dam

Description: _____

Number: 18 (79) Date 3/5 (9:30 a.m.)

Subject: Gillespie Dam

Description: _____

Number: 19 (80) Date 3/5 (10 a.m.)

Subject: Holly Acres

Description: 115th Avenue and Gila River)

Maybe Allenville (south of Buckeye)

Number: 20 (81) Date 3/5 (10:30 a.m.)

Subject: Vicinity of Holly Acres

Description: _____

Number: 20A (82) Date 3/5 (11 a.m.)

Subject: Sky Harbor Airport

Description: South runway looking west

Number: _____ Date _____

Subject: _____

Description: _____

Number: _____ Date _____

Subject: _____

Description: _____

Number: _____ Date _____

Subject: _____

Description: _____

CONTACT SHEET # 8 - NEGATIVES

Contact Sheet #9

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM



→ 0

→ 1

→ 1A

→ 2

→ 2A

→ 3

→ 3A

→ 4

0

5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK S7



→ 7

→ 5

→ 5A

→ 6

→ 6A

→ 7

→ 7A

→ 8

→ 8A


→ 9

AFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062



→ 9A

→ 10

→ 10A

→ 11

→ 11A

→ 12

→ 12A

→ 13

→ 13A

→ 14

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062



→ 14A

→ 15

→ 15A

→ 16

→ 16A

→ 17

→ 17A

→ 18

→ 18A

→ 19

Number: 0 (83) Date 3/4/78Subject: Cave Creek DamDescription: Looking east.Number: 1 (84) Date 3/4/78Subject: Cave Creek DamDescription: Looking east.Number: 2 (85) Date 3/4/78Subject: Cave Creek DamDescription: Highest water level, southeastNumber: 3 (86) Date 3/4/78Subject: Cave CreekDescription: Outlet area looking east.Number: 4 (87) Date 3/4/78Subject: Cave Creek DamDescription: Closeup of buttress
looking north.Number: 5 (88) Date 3/4/78Subject: Cave Creek DamDescription: Water seepage, north sideNumber: 6 (89) Date 3/4/78Subject: Cave Creek DamDescription: Jim Roney at outlet looking
east.Number: 7 (90) Date 3/4/78Subject: Cave Creek DamDescription: Outlet at full capacity

Number: 8 (91) Date 3/4/78

Subject: Cave Creek Dam

Description: Outlet area looking south.

Number: 9 (92) Date 3/4/78

Subject: Cave Creek Dam

Description: Outlet area looking south.

Number: 10 (93) Date 3/4/78

Subject: Cave Creek Dam

Description: Outlet area looking west.

Number: 11 (94) Date 3/4/78

Subject: Cave Creek Dam

Description: Looking east.

Number: 12 (95) Date 3/4/78

Subject: Cave Creek Dam

Description: Looking north-northeast

Number: 13 (96) Date 3/4/78

Subject: Cave Creek Dam

Description: Looking north-northeast

Number: 14 (97) Date 3/4/78

Subject: Cave Creek Dam

Description: Looking northeast

Number: 15 (98) Date 3/4/78

Subject: Cave Creek Dam

Description: Water backed up, northwest

Number: 16 (99) Date 3/4/78

Subject: Cave Creek Dam

Description: Air National Guard helicopter
looking east

Number: 17 (100) Date 3/4/78

Subject: Cave Creek Dam

Description: Air National Guard helicopter
looking north

Number: _____ Date _____

Subject: _____

Description: _____

Contact Sheet #9 - Negatives

Number: 1 (101) Date _____

Subject: Salt River flowing through Phoenix

Description: Looking south-southwest at
downtown Phoenix showing Salt River flow

Number: 2 (102) Date _____

Subject: CAP Aqueduct

Description: _____

Number: 3 (103) Date _____

Subject: Cave Creek Dam Reservoir area

Description: _____

Number: 4 (104) Date _____

Subject: Cave Creek Dam

Description: Looking downstream from dam.

Number: 5 (105) Date _____

Subject: Cave Creek Dam and Reservoir

Description: _____

Number: 6 (106) Date _____

Subject: Cave Creek Dam

Description: Looking downstream at Cave
Creek Dam and Cave Creek

Number: 7 (107) Date _____

Subject: Cave Creek Dam Outlet

Description: _____

Number: 8 (108) Date _____

Subject: Cave Creek and Arizona Canal

Description: Flow in Cave Creek at
Arizona Canal and spillage at Spillway 8
causing flooding to the south. Photo
taken looking upstream of Arizona Canal.

Number: 9 (109) Date _____

Subject: Cave Creek Flow

Description: Vicinity of Royal Palm

School and 19th Avenue

Number: 10 (110) Date _____

Subject: Cave Creek flows below AZ Canal

Description: Vicinity of 19th Avenue

and Northern.

Number: 11 (110) Date _____

Subject: New River & Glendale Avenue

Description: Looking downstream on New

River. Glendale Avenue Bridge left center

of photo.

Number: 12 (112) Date _____

Subject: Gila & Agua Fria Confluence

Description: Looking south across

Gila.

Number: 13 (113) Date _____

Subject: Gila & Agua Fria Confluence

Description: Looking upstream of Gila

Number: 14 (114) Date _____

Subject: Gila River

Description: _____

Number: 15 (115) Date _____

Subject: Gila River looking upstream

Description: _____

Number: 16 (116) Date _____

Subject: Allenville - Gila Flow

Description: Looking downstream

Number: 17 (117) Date _____

Subject: Helicopter pad

Description: Herb Donald and Hawley
Atkinson

Number: 18 (118) Date _____

Subject: Holly Acres - 123 Ave & Gila River

Description: Flooding of Holly Acres
located at southeast corner of 123 Avenue
and Southern. Looking north, note
highwater marks.

Number: 19 (119) Date _____

Subject: Salt River - Mill Ave Bridge

Description: Looking North

Number: 20 (120) Date _____

Subject: Scottsdale Rd Bridge & Salt River

Description: Looking upstream

Number: 21 (121) Date _____

Subject: Mill Ave Bridge & Salt River

Description: Looking downstream.

Number: _____ Date _____

Subject: _____

Description: _____

Number: _____ Date _____

Subject: _____

Description: _____

Number: _____ Date _____

Subject: _____

Description: _____

Contact sheet #11



KODAK SAFETY FILM 5035

KODAK SAFETY FILM 8035

KODAK SAFETY FILM 8035



<p>Number: <u>0A (122)</u> Date <u>4-13-77</u></p> <p>Subject: <u>Retarding structure on a maj.</u></p> <p>Description: <u>tributary to Veko1 wash.</u></p> <p><u>Height greater than 10 ft. Length</u></p> <p><u>unknown. Pertains to 0A thru 4A.</u></p> <p><u>Facing east on top of structure.</u></p>	<p>Number: <u>5A (127)</u> Date <u>4-13-77</u></p> <p>Subject: <u>Interstate-8 bridge over Veko1</u></p> <p>Description: <u>Wash.</u></p> <p><u>All photos taken from upstream side</u></p> <p><u>of bridge.</u></p>
<p>Number: <u>1A (123)</u> Date <u>4-13-77</u></p> <p>Subject: _____</p> <p>Description: <u>Facing south from north</u></p> <p><u>(downstream) side of structure.</u></p>	<p>Number: <u>6A (128)</u> Date <u>4-13-77</u></p> <p>Subject: <u>Interstate-8 bridge over Veko1</u></p> <p>Description: <u>Wash.</u></p> <p><u>All photos taken from upstream side</u></p> <p><u>of bridge.</u></p>
<p>Number: <u>2A (124)</u> Date <u>4-13-77</u></p> <p>Subject: _____</p> <p>Description: <u>Facing southwest from</u></p> <p><u>north side of structure.</u></p>	<p>Number: <u>7A (129)</u> Date <u>4-13-77</u></p> <p>Subject: <u>Interstate-8 bridge over Veko1</u></p> <p>Description: <u>Wash.</u></p> <p><u>All photos taken from upstream side</u></p> <p><u>of bridge.</u></p>
<p>Number: <u>3A & 4A</u> Date <u>4-13-77</u></p> <p>Subject: <u>(125), (126)</u></p> <p>Description: <u>Combine for panoramic view</u></p> <p><u>from top of structure from east (left</u></p> <p><u>side of 3A) to southeast (right side</u></p> <p><u>of 4A.)</u></p>	<p>Number: _____ Date _____</p> <p>Subject: _____</p> <p>Description: _____</p>

Contact Sheet #11 -

Negatives

contact sheet # 12

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062



→14A

→15

→15A

→16

→16A

→17

→17A

→18

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062



→10A

→11

→11A

→12

→12A

→13

→13A

→14

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062



→6A

→7

→7A

→8

→8A

→9

→9A

→10

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062



→2A

→3

→3A


→4

0 9 /


→5

→5A

→6



KODAK SAFETY FILM 5062



→0

→0A

→1

→1A

→2

→18A

→19

→19A

→20

→20A

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062



Number: 0 Date 2/78
Subject: Sid Brase
Description: _____

Number: 1 Date 2/78
Subject: Sid Brase
Description: _____

Number: 2 Date 2/78
Subject: John Rodriguez
Description: _____

Number: 3 Date 2/78
Subject: Nick Karan
Description: _____

Number: 4 Date 2/78
Subject: Larry Wong
Description: _____

Number: 5 Date 2/78
Subject: John Greisiger
Description: _____

Number: 6 Date 2/78
Subject: Dorie Perez
Description: _____

Number: 7 Date 2/78
Subject: Dorie Perez
Description: _____

PHOTO CAPTION SHEET

Number: 8 Date 2/78
Subject: Doris Taylor
Description: _____

Number: 9 Date 2/78
Subject: Doris Taylor
Description: _____

Number: 10 Date 2/78
Subject: Emily Marek
Description: _____

Number: 11 Date 2/78
Subject: Linda Young
Description: _____

Number: 12 Date 2/78
Subject: Linda Young
Description: _____

Number: 13 Date 2/78
Subject: Dan Sagramoso
Description: _____

Number: 14 Date 2/78
Subject: Sue Mutschler
Description: _____

Number: 15 Date 2/78
Subject: Bob Ward
Description: _____

PHOTO CAPTION SHEET

Number: 16 Date 2/78
Subject: John Savicky
Description: _____

Number: 17 Date 2/78
Subject: Ervin McLuty
Description: _____

Number: 18 Date 2/78
Subject: John Wiyse1
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____


Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____


Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

CONTACT SHEET # 12



35MM 135 1:1.7



35MM PRINTS
C.FINE #25201

contact sheet #13

KODAK SAFETY FILM 5062



5A

→ 16

KODAK SAFETY FILM 5062



→ 16A

→ 17



→ 17A

→ 18

KODAK SAFETY FILM 5062



→ 18A

→ 19

KODAK SAFETY FILM 5062



→ 19A

→ 20

→ 20A

SAFETY FILM 5062



0A

→ 11

KODAK SAFETY FILM 5062



→ 11A

→ 12

KODAK SAFETY FILM 5062



→ 12A

→ 13

KODAK SAFETY FILM 5062



→ 13A

→ 14

ILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK



5A

→ 6



→ 6A

→ 7



→ 7A

→ 8



→ 8A

→ 9



→ 9A

→ 10

→ 1

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY FILM 5062

KODAK SAFETY F



→ 0A

→ 1



→ 1A

→ 2



→ 2A

→ 3



→ 3A

→ 4

1 4 2



→ 5

→

Number: 1 thru 20 Date 3/28/78
Subject: Spook Hill Ground Breaking
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

Number: _____ Date _____
Subject: _____
Description: _____

Spook Hill Groundbreaking

CLINE 7/23/73
35MM 138113





Spook Hill Groundbreakings

3-28-78

FLINT 2244
35MM PLATES



3-28-78

SPOOK HILL GROUND BREAKING

3-28-78

SPOOK HILL GROUNDBREAKING

3-28-78

SPOOK HILL GROUND BREAKING

3-28-78


SPOOK HILL GROUND BREAKING

SPOOK HILL
GROUNDBREAKING
PICTURES & NEGATIVES

CONTACT SHEET #14



KODAK SAFETY FILM 5062



KODAK SAFETY FILM 5062



KODAK SAFETY FILM 5062



KODAK SAFETY FILM 5062



KODAK SAFETY FILM 5062



KODAK SAFETY FILM 5062

Gila River Watershed
and Project Map


CONTACT SHEET # 14
PICTURES & NEGATIVES

STAMP PRINTS





35MM PRINTS
C-FIVE 40284




130

INDIAN SCHOOL RD OVER
AGUA FRIA RIVER. 3/79

132

CAVE BUTTES
DAM IMPOUNDMENT
1979, MARLA



132



CAVE BUTTES DAM
OUTLET WORKS.

2-17-80