

SOUTH MOUNTAIN
PHOTOGRAPHS

007.123

11/20/64

South Mountain

Gravel pit at
Mineral Rd. and
Central Ave.

Property of
Flood Control District of MC Library
Please Return to
2801 W. Durango
Phoenix, AZ 85009



Site of possible
retention dam across
wash. Looking south
about 19th St. at road
leading to Heard Boy
Scout Pueblo.



View of wash across
Piedmond about 10th
Ave., looking south.



11/20/64

South Mountain

View of McNeil Ave,
looking east at about 5th
Ave., showing wash which
flows into McNeil.



Wash south of McNeil Ave.,
east. Tape is at about level
last high water.



7th Ave. Road
eroded by water
in wash which crosses
south of McNeil Ave.






December 2, 1964 - South Mountain area 7th Avenue, looking west,
south of McNeil. Erosion caused by high water in wash from
South Mountain.



December 2, 1964 - South Mountain area gravel pit at Central Avenue and Mineral Road.



December 2, 1964 - Wash from South Mountains. At this point is parallel to McNeil Ave. Tape indicates height of 1st high water. Looking upstream.