Maricopa County Flood Insurance Study & Flood Photos

1990-91

GILA BEND FLOOD INSURANCE STUDY

Aerial of Sand Tank and Bender Wash.

Sand Tank Wash crossing at I–8.

Sand Tank Wash Pima Street Crossing.

Sand Tank Wash Gila Bend Canal Crossing.

Scott Avenue Wash at Railroad crossing.

Scott Avenue Wash crossing at Pima Street.

DEADMAN WASH FLOOD INSURANCE STUDY.

Deadman Wash East of I–17 (upstream).

Deadman wash at Road to Federal Prison.

Same location as previous picture.

Deadman Wash at access road below I–17.

Same location as previous picture.

Looking upstream at I–17 bridge.

FLOODING AT DEADMAN WASH AREA 03-01-91

Deadman Wash at I-17 (upstream).

New River at Access Road above I-17.

Deadman Wash at 39th Ave.

& Desert Hills Rd.

East channel Deadman Wash

at Carefree Highway.

West channel Deadman

Wash at Carefree Highway

LUKE WASH FLOOD INSURANCE STUDY.



Aerial of Luke Wash at the railroad crossing.

Closeup of the same area as previous picture.

Luke Wash at the railroad crossing.

Aerial of Luke Wash crossing the SR85.

Same area as the previous picture.