Property of
Flood Control District of MC Library
Please Return to
2801 W. Durango
Phoenix, AZ 85009

MCMICKEN

NORTH BREACH

McMicken
North Breach

#1

#2

McMicken
North
Breech

#3

#4

PHOTO CAPTION SHEET

Number: 1 Date 8/3/78

Subject: McMicken Dam North Breach

Description: Looking north from top of dike. Photo shows erosion before backfilling.

Number: 2 Date 8/3/78

Subject: McMicken Dam North Breach

Description: Looking West-Northwest before backfilling.

Number: 3 Date 8/3/78

Subject: McMicken Dam North Breach

Description: Looking West before backfilling

Number: 4 Date 8/3/78

Subject: McMicken Dam North Breach

Description: Looking West-Southwest before backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
North
Breach

#5

#6

McMicken
North
Breach

7

8

PHOTO CAPTION SHEET

Number: 5 Date 8-3-78

Subject: McMicken North Breach

Description: Looking South before backfilling

Number: 7 Date 8/3/78

Subject: McMicken North Breach

Description: Looking North at borrow pit area (60' x 200')

Number: 6 Date 8/3/78

Subject: McMicken North Breach

Description: Looking Southeast before backfilling

Number: 8 Date 8/3/78

Subject: McMicken North Breach

Description: Looking South at borrow pit area (60' x 200')

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
North
Breach

#9

#10

McMicken
North
Breach

#11

#12

PHOTO CAPTION SHEET

Number: 9 Date 8/4/78

Subject: McMicken North Breach

Description: Looking North-Northeast after one day backfilling

Number: 11 Date 8/4/78

Subject: McMicken North Breach

Description: Looking West-Northwest after one day backfilling

Number: 10 Date 8/4/78

Subject: McMicken North Breach

Description: Looking north after one day backfilling

Number: 12 Date 8/4/78

Subject: McMicken North Breach

Description: Looking West after one day backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
North
Breach

13

14

McMicken
North
Breach

#15

#16

PHOTO CAPTION SHEET

Number: 13 Date 8/4/78

Subject: McMicken North Breach

Description: Looking West-Southwest after one day backfilling

Number: 15 Date 8/4/78

Subject: McMicken North Breach

Description: Looking Southeast after one day backfilling

Number: 14 Date 8/4/78

Subject: McMicken North Breach

Description: Looking South after one day backfilling

Number: 16 Date 8/7/78

Subject: McMicken North Breach

Description: Looking North-Northeast after two days of backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
North
Breach

#17

#18

McMicken
North
Breach

#19

#20

PHOTO CAPTION SHEET

Number: 17 Date 8/7/78

Subject: McMicken North Breach

Description: Looking North after two days backfilling

Number: 19 Date 8/7/78

Subject: McMicken North Breach

Description: Looking West after two days backfilling

Number: 18 Date 8/7/78

Subject: McMicken North Breach

Description: Looking West-Northwest after two days backfilling

Number: 20 Date 8/7/78

Subject: McMicken North Breach

Description: Looking West-Southwest after two days backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
North
Breach

#21

#22

McMicken
North
Breach

#23

#24

PHOTO CAPTION SHEET

Number: 21 Date 8/7/78

Subject: McMicken North Breach

Description: Looking South after two days backfilling

Number: 23 Date 8/7/78

Subject: McMicken North Breach

Description: Looking South after two days backfilling

Number: 22 Date 8/7/78

Subject: McMicken North Breach

Description: Looking South after two days fackfilling

Number: 24 Date 8/7/78

Subject: McMicken North Breach

Description: Looking Southeast after two days backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
North
Breach

#25

#26

McMicken
North
Breach

#27

#28

PHOTO CAPTION SHEET

Number: 25 Date 8/7/78

Subject: McMicken North Breach

Description: Looking South at borrow pit after two days work

Number: 27 Date 8/8/78

Subject: McMicken North Breach

Description: Looking North-Northeast after three days work

Number: 26 Date 8/7/78

Subject: McMicken North Breach

Description: Looking North after two days work

Number: 28 Date 8/8/78

Subject: McMicken North Breach

Description: Looking North after three days backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
North
Breach

#29

#30

McMicken
North
Breach

#31

#32

PHOTO CAPTION SHEET

Number: 29 Date 8/8/78

Subject: McMicken North Breach

Description: Looking North-Northwest after three days backfilling

Number: 31 Date 8/8/78

Subject: McMicken North Breach

Description: Looking West-Southwest after three days backfilling

Number: 30 Date 8/8/78

Subject: McMicken North Breach

Description: Looking West after three days backfilling

Number: 32 Date 8/8/78

Subject: McMicken North Breach

Description: Looking Southwest after three days backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
North Breach

#33

#34

McMicken
North Breach

35

#36

PHOTO CAPTION SHEET

Number: 33 Date 8/8/78

Subject: McMicken North Breach

Description: Looking South after three days backfilling

Number: 35 Date 8/8/78

Subject: McMicken North Breach

Description: Looking Southeast after three days backfilling

Number: 34 Date 8/8/78

Subject: McMicken North Breach

Description: Looking South after three days backfilling

Number: 36 Date 8/8/78

Subject: McMicken North Breach

Description: Looking North at borrow pit after three days work

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
North Breach

#37

#38

McMicken
North Breach

#39

#40

PHOTO CAPTION SHEET

Number: 37 Date 8/8/78

Subject: McMicken North Breach

Description: Looking South at borrow pit after three days work

Number: 38 Date 8/10/78

Subject: McMicken North Breach

Description: Looking North-Northeast after completion of backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: 39 Date 8/10/78

Subject: McMicken North Breach

Description: Looking West after completion of backfilling work

Number: 40 Date 8/10/78

Subject: McMicken North Breach

Description: Looking North after completion of backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
North Breach

#41

PHOTO CAPTION SHEET

Number: 41 Date 8/10/78

Subject: McMicken North Breach

Description: Looking Southeast after completion of backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

MCMICKEN

SOUTH BREACH

McMicken
South Breach

#1

#2

McMicken
South Breach

#3

#4

PHOTO CAPTION SHEET

Number: 1 Date 8/3/78

Subject: McMicken . South Breach

Description: Looking Northeast before backfilling

Number: 3 Date 8/3/78

Subject: McMicken . South Breach

Description: Looking West before backfilling.

Number: 2 Date 8/3/78

Subject: McMicken. South Breach

Description: Looking North before backfilling

Number: 4 Date 8/3/78

Subject: McMicken . South Breach

Description: Looking South before backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
South Breach

#5

#6

McMicken
South
Breach

#7

#8

PHOTO CAPTION SHEET

Number: 5 Date 8/3/78

Subject: McMicken South Breach

Description: Looking South before backfilling.

Number: 7 Date 8/3/78

Subject: McMicken South Breach

Description: Borrow pit area looking West

Number: 6 Date 8/3/78

Subject: McMicken South Breach

Description: Borrow pit over South

Number: 8 Date 8/11/78

Subject: McMicken South Breach

Description: Looking North after two days backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
South Breach

#9

#10

McMicken
South Breach

#11

#12

PHOTO CAPTION SHEET

Number: 9 Date 8/11/78

Subject: McMicken South Breach

Description: Looking North after two days backfilling

Number: 11 Date 8/11/78

Subject: McMicken South Breach

Description: Looking South after two days backfilling

Number: 10 Date 8/11/78

Subject: McMicken South Breach

Description: Looking West after two days backfilling

Number: 12 Date 8/11/78

Subject: McMicken South Breach

Description: Looking South after two days backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
South
Breach

#13

#14

McMicken
South
Breach

#15

#16

PHOTO CAPTION SHEET

Number: 13 Date 8/11/78

Subject: McMicken South Breach

Description: Looking West second day of backfilling

Number: 15 Date 8/11/78

Subject: McMicken South Breach

Description: Borrow pit after two days work looking west.

Number: 14 Date 8/11/78

Subject: McMicken South Breach

Description: Looking West borrow pit

Number: 16 Date 8/14/78

Subject: McMicken South Breach

Description: Looking North after third day of backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
South
Breach

17

18

McMicken
South
Breach

#19

#20

PHOTO CAPTION SHEET

Number: 17 Date 8/14/78

Subject: McMicken South Breach

Description: Looking North after third day of backfilling

Number: 19 Date 8/14/78

Subject: McMicken South Breach

Description: Looking South after third day of backfilling

Number: 18 Date 8/14/78

Subject: McMicken South Breach

Description: Looking West after third day of backfilling

Number: 20 Date 8/14/78

Subject: McMicken South Breach

Description: Looking South after third day backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

McMicken
South
Breach

#21

#22

McMicken
South
Breach

23

#24

PHOTO CAPTION SHEET

Number: 21 Date 8/14/78

Subject: McMicken South Breach

Description: Close-up of fill stake

Number: 22 Date 8/14/78

Subject: McMicken South Breach

Description: Looking West after third day of backfilling

Number: 23 Date 8/14/78

Subject: McMicken South Breach

Description: Looking West after third day of work.

Number: 24 Date 8/16/78

Subject: McMicken South Breach

Description: Looking North after completion of backfilling

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

Number: Date

Subject:

Description:

3/3/78 Old Cross Cut Canal
View of notch formed in bank protection concrete under Misc. Improvements contract. At station 71+00 bridge to trailer court. Approximately 2cy hole eroded out behind this slab.

67

3/3/78 Old Cross Cut Canal
View of canal looking upstream from structure at station 94+00 near Holly Street.

3/3/78 Old Cross Cut Canal
View of drop structure at station 23+00.

3/3/78 Salt River
View of Salt River looking downstream from Scottsdale Road bridge--showing the progress of the flow from the very first releases.

3/3/78 Salt River
View of Salt River looking upstream from Scottsdale Rd. bridge--showing inundation of dry river bed with first releases.

3/5/78 Sky Harbor Airport south runway looking west

3/5/78

Salt River at Mill Avenue Bridge looking north.

(2)

3/8/78 Salt River Channel
View of washed out rock & mortar chute structure incorporated with bike path on the north bank of river immediately downstream of the Scottsdale Road bridge at Salt River.

(3)

3/8/78 Salt River Channel
View of washed out bike path and bank erosion along the north bank of Salt River as seen looking west from underneath the Scottsdale Road bridge.

(4)

3/8/78 Salt River Channel
View of debris at high water level and broken up bike path concrete placed under IBW project, immediately upstream of Scottsdale road bridge.

(5)

3/8/78 Salt River Channel
View of north bank of Salt River at Papago Stables showing washed out fencing, Tempe bike path and bank erosion. View looking west toward Mill Avenue bridge.

(6)

3/8/78 Salt River Channel
View of north bank of Salt River immediately downstream of Scottsdale Road bridge showing washed out Tempe bike path and bank erosion downstream of bridge toward Papago Stables.

3/13/78 Salt River Flood Damage. View of front of Systems Wire & Cale Mfg. firm at 28th St. and Elwood. Note debris and mud--this bldg. has about 3 feet of water in it.

3/13/78 Salt River Flood Damage. View of cable tray system across river bed at Systems Wire and Cable Mfg. at 28th St. and Elwood.

3/13/78 Salt River Flood Damage. View looking east from river bed of Systems Wire & Cable Mfg. firm at 28th St. and Elwood. Freeway bridge in background.

3/13/78 Salt River Flood Damage. View of east end of main run-way at Sky Harbor Airport. View looking south-west toward Nat'l Guard Hangar.

13

3/13/78 Salt River Flood Damage. View of ASU parking lot facility as seen looking east from Mill Avenue bridge.

73

14

3/13/78 Salt River Channel. View of channel showing north bank as seen from Mill Avenue bridge.

15

3/13/78 Salt River Channel View of channel showing erosion along south bank between channel and where ASU located athletic parking lot.

16

3/13/78 Salt River. View looking north of re-building of river channel by M.M. Sundt Contractors immediately upstream of Country Club Drive crossing.

14

17

3/13/78 Salt River. View looking north of M.M. Sundt re-building dikes and making channel repairs for Salt River immediately upstream of Country Club Drive crossing.

15

(16)

3/13/78 Salt River Crossing at Country Club Drive. View of City of Mesa repair trucks.

19

3/13/78 McKellips Road Crossing. View looking easterly of Salt River crossing at McKellips Rd.

(17)

20

(18)

3/13/78 McKellips Road Crossing at Salt River. View looking westerly of McKellips Road on est bank of Salt River.

21

3/13/78 Country Club Drive
View of dozer placing materials in downstream shoulder of Country Club Drive crossing over Salt River looking easterly.

22

3/13/78 Salt River Flooding. View looking south from Papago Stable showing bank erosion along north bank of Salt River channel between Scottsdale Road and Mill Ave. Arrow in upper center of photo points to a well casing which was 100 ft. back from bank edge prior to flooding.

23

3/13/78 Salt River Flooding. View of ASU parking lot area looking west from east shoulder of Scottsdale Road.

24

3/13/78 Salt River Flooding. View looking west just prior to crossing river showing silt and debris washed in to cover-up McKellips Road, Salt River crossing.

3/13/78 Salt River Flooding. View looking west just prior to crossing river, showing debris and silt covering up paving on McKellips Road.

Salt River Flooding. 3/13/78 View looking north of the Alma School road showing conveyor system washed out by Johnson and Stewart Materials plant.

3/13/78 Salt River Flooding. View of Alma School Road and damage looking north, prior to crossing river, showing Salt River Project installing new power pole line.

3/13/78 Salt River Flooding. View of north bank of Improved channel of Salt River at Papago Stables showing fencing and concrete from Tempe Bike Path in river bed.

3/14/78 Salt River Flood Damage. View of south approach to bridge showing the amount of resurfacing that was replaced on new approach.

28

3/14/78 Salt River Flood Damage. View of 24th Street bridge after repairs completed--both approaches rebuilt, beside temporary hand rails.

31

3/14/78 Salt River Flood Damage. View of 7th Street bridge showing both approaches being rebuilt as seen from downstream south bank.

29

32

30

3/14/78 Salt River Flood Damage. View of repaired 7th Avenue bridge looking north-west from upstream south bank.

33

3/14/78 Salt River Flood Damage. View of 16th Street bridge crossing as seen from south bank and downstream of bridge.

34

3/14/78 Salt River Flood Damage. View of north approach to bridge showing storm drain and aggregate processing plant in rear.

80

35

3/14/78 Salt River Flood Damage. View of 16th Street bridge as seen from river bed directly downstream.

36

(34)

3/14/78 Salt River Flood Damage. View of 16th Street Bridge as seen from north bank.

57

3/15/78 Salt River Flood Damage. View of bridge over main channel along north bank after repairs on 35th Avenue completed.

81

(36)

38

(36)

3/15/78 Salt River Flood Damage. View of 35th Avenue bridge over main channel after approaches re-built and new hand rails of wood.

39

37

3/15/78 Salt River Flood Damage. View of north side of Heflin Steel Co. bldg. on south bank of river and upstream of bridge.

40

38

3/15/78 Salt River Flood Damage. Close-up view of City of Phoenix sewer line just downstream 51st Avenue showing section under repair afer damage by river flow.

82

41

39

3/15/78 Salt River Damage. View of river crossing at 51st Avenue as seen from downstream to upstream - county highway making repairs to road-bed and bridge approaches.

42

40

3/15/78 Salt River Flood Damage. View of City of Phoenix sewer line just downstream of 51st Avenue showing section of line under repair as viewed from upstream to downstream.

43

3/15/78 Salt River Flood Damage. View of 51st Ave. crossing under repair by County Highway crew looking from south to north.

83

41

44

42

3/15/78 Salt River Flood Damage. View of SRP equipment repairing pole line at 43rd Avenue crossing View looking south from north bank.

45

GILA RIVER FLOOD DAMAGE PHOTOS

January 4, 1979

Roll 1

0. Erosion of 107th Avenue, looking west, approximately 100 yards north of the river bank.

1. Erosion of 107th Avenue, looking north, approximately 100 yards north of the river bank.

2. House on 107th Avenue, approximately 200 yards north of the river bank, west side. Note exposed septic tank.

3. North bank of river at 115th Avenue looking east. New channel has been cut to the north of vegetation and silt clogged old channel.

4. North bank of river at 115th Avenue looking southwest. New channel has been cut to the north.

5. North bank of river at 115th Avenue looking west. New channel has been cut to the north.

6. At 115th Avenue looking south across new channel at house deposited in old channel vegetation.

7. Erosion of 115th Avenue 100 yards north of new channel, looking southwest across farm land.

8. North bank of river at El Mirage Road (123rd Avenue), looking east. New channel has been cut to the north.

9. North bank of river at El Mirage Road (123rd Avenue),looking west. New channel has moved north.

10. North bank of the river at Bullard Road (147th Avenue) looking east. Channel has broadened to the north.

11. Bullard Road (147th Avenue) looking south at Casey Abbott Park entrance.

12. North bank of the river at Bullard Road (147th Avenue) looking west as channel broadens.

13. North bank of the river at Cotton Lane (171st Avenue) looking east. New channel has moved north. Note old channel in background.

14. North bank of the river at Cotton Lane (171st Avenue) looking southwest. Old channel in far background.

15. North bank of the river at Cotton Lane (171st Avenue) looking west. Channel has eroded to the north.

16. Airport Road (211th Avenue) 50 yards south of Beloat Road looking southwest at feedlot damaged by flood.

17. Airport Road (211th Avenue) 50 yards south of Beloat Road looking south. River channel 1/2 mile south.

18. North bank of river at Watson Road (235th Avenue) looking east at bank erosion of new channel.

19. North bank of new channel at Watson Road (235th Avenue) looking south.

20. At Watson Road, north of new channel, looking east.

Roll 2

1. Palo Verde Road (291st Avenue) at small bridge, looking south.

2. Palo Verde Road (291st Avenue) at small bridge, looking southwest.

3. Palo Verde Road (291st Avenue) at small bridge, looking southeast.

4. Ray Road west of 391st Avenue looking southeast across cotton field toward Powers Butte. River channel has moved north into cotton field.

5. Same as 4.

6. Arlington School Road (339th Avenue) about 1/2 mile south of the school, looking northeast toward Powers Butte. New channel has cut to the west of overgrown old channel area.

7. Same as 6 looking east.

8. At intersection of Arlington School Road and Desert Rose Road, looking southeast. New channel has moved west of overgrown old channel.

9, 10, 11, & 12. Gillespie Dam from south on old highway 80 bridge. Note riverbed and vegetation is higher than the dam.

13. Old highway 80 dip crossing below Gillespie Dam, looking east.

14, 15. Gillespie Dam from hill overlooking west abutment looking east.

16. At Gillespie Dam looking north toward Powers Butte. Note vegetation in reservoir area.

17. At Gillespie Dam looking northwest. Arlington Canal on west edge of the reservoir area.

18. At Gillespie Dam looking southeast. Old highway 80 bridge & gasline suspension structures show.

19. North of Gillespie Dam, looking east across fields toward reservoir area and Buckeye Hills.

61A

1/1/79 North bank of [redacted] River at 115th Avenue looking east. New channel has been cut to the north of vegetation and silt clogged old channel.

1/4/79 North bak of Gila River at 115th Avenue looking southwest. New channel has been cut to the north through farmland irrigated 300-400 feet wide and perhaps 20 feet deep. Channel has left the growth in the river cause water can't get through.

1/4/79 North bank of river at El Mirage Road (123rd Avenue), looking east. New channel has been cut to the north.



1/4/79 North bank of river at El Mirage Road (123rd Avenue) looking west. New channel has moved north.



1/4/79 North bank of the river at Bullard Road (147th Avenue) looking east. Channel has broadened to the north.

1/4/79 North bank of the river at Cotton Lane (171st Avenue) looking east. New channel has moved north. Note old channel in background.



1/4/79 North bank of the river at Cotton Lane (171st Avenue) looking west. Channel has eroded to the north.

1/4/79 North bank of river at Watson Road (235th Avenue) looking east at bank erosion of new channel.



1/4/79 North bank of new channel at Watson Road (235th Avenue) looking south.

Jan 4, 1979 At Watson Road, north of new channel, looking east.

1/4/79 Bullard Road(147th Avenue) looking south at Casey Abbott Park entrance.



1/4/79 North bank of the river at Bullard Road (147th Avenue) looking west as channel broadens.





Agua Fria looking northeasterly
at Hound Dog Acres from
transmission tower alignment
2/22/80

Agua Fria looking upstream at
Hound Dog Acres from
transmission tower alignment
2/22/80



Agua Fria looking upstream at west bank from transmission tower alignment 2/22/80

Agua Fria looking northeast at
Hound Dog Acres 2/22/80

Agua Fria looking upstream
along east bank south of
Thomas Road 2/22/80

Agua Fria Hound Dog Acres
looking N.E. vicinity of
109th Ave. 2/22/80

Agua Fria looking upstream
along west bank at Pinnacle
Peak Road alignment 2/22/80





Agua Fria River - Hatfield (Hound Dog) Acres (looking northeasterly) 2/22/80



Agua Fria looking upstream at
Hound Dog Acres in vicinity
of 109th Avenue 2/22/80

Agua Fria looking upstream at
Hound Dog Acres 2/22/80



Agua Fria looking upstream at Hound Dog Acres in vicinity of 109th Avenue 2/22/80



Agua Fria River - Hatfield
(Hounddog) Acres
Looking upstream 2/22/80

Agua Fria looking upstream
from Union Hills Drive 2/22/80

Agua Fria River looking
upstream from Thomas Road
2/22/80



Agua Fria looking upstream at Hounddog Acres from Pinnacle Peak Road 2/22/80



Agua Fria River looking
upstream from Thomas Road
2/22/80



Agua Fria River looking NE
south of Thomas Road 2/22/80

Agua Fria looking upstream
at Thomas Rd east bank
2/22/80

Agua Fria looking upstream
at remnants of Agua Fria
Sand & Rock 2/22/80

Agua Fria looking upstream
just above Thomas Road
2/22/80



Agua Fria River looking ustream
from just north of McDowell Rd
2/22/80



Agua Fria looking N.E. just above McDowell Road
2/22/80

Agua Fria looking upstream at Rose Garden Lane 2/22/80
2/22/80
Agua Fria looking upstream at Rose Garden Lane vicinity
2/22/80

Agua Fria looking upstream at
Rose Garden Lane 2/22/80

Agua Fria River - Rose Garden Lane Vicinity (looking westerly)
Note: Erosion that has occurred dangerously close to residence.
February 22, 1980

Looking NE Rose Garden Estates
2/22/80

2/22/80
Agua Fria looking upstream along
east bank at Rose Garden Lane



Agua Fria looking northwesterly
from Rose Garden Lane 2/22/80



Agua Fria looking downstream
from Rose Garden Lane 2/22/80

Agua Fria looking downstream
from Rose Garden Lane 2/22/80



Agua Fria looking downstream
from Rose Garden Lane 2/22/80

Agua Fria looking upstream from
Beardsley Road 2/22/80





2/17/80 Cave Buttes Dam

2/17/80 Cave Buttes Dam Reservoir & Old Cave Creek Dam



2/17/80 Cave Buttes Dam & Reservoir w/Cave Creek Dam

2/17/80 Cave Buttes Dam & Cave Creek Dam

2/17/80 CAve Creek Dam & Reservoir

2/17/80 Cave Creek Dam w/Cave Buttes Dam in background

2/17/80 Cave Crek Dam w/by-pass spillway in foreground

2/17/80 Casey Abbot Park - Sierra Estrella Golf Course



2/17/80 Gila River - Gillespie Dam looking southerly.

2/22/80 Gila/Salt Rivers - Vicinity of Confluence (looking downstream)
Note: Two distinct main channels downstream of 107th Avenue. Holly Acres upper right hand corner.

2/22/80 Salt-Gila confluence looking southwesterly at 115th Avenue.

2/22/80 Salt-Gila confluence looking downstream from about 111th Avenue.

2/22/80 Gila River looking northwesterly at 119th Avenue.

2/22/80 Gila River looking westerly at Holly Acres (123rd Avenue)

2/22/80 Gila River looking downstream north bank from about 107th Avenue.

2/22/80 Gila River - 115th Avenue (looking northwesterly)
Note: Significance of northerly channel and continuing erosion.



2/17/80 Stewart Mountain Dam Salt River/Saguaro Lake

2/17/80 Stewart Mountain Dam - Salt River

2/22/80 Salt River at 59th Avenue looking northeast.

2/22/80 Salt River - 59th Avenue (looking northeasterly)
Note: Sand and gravel operation encroaching on channel.



2/22/80 Salt River looking northwest at SRP landfill at 67th Avenue.

2/22/80 Salt River - 67th Avenue (looking upstream)
Note: Residences in background along 67th Avenue.
Erosion along southerly bank swept three residences away
that were located north of remaining residences.

2/22/80 Salt River looking upstream at 67th Avenue.

2/22/80 Salt River just upstream of 67th Avenue looking northwest.

2/22/80 Salt River looking upstream from about 71st Avenue.
(67th Avenue upper right corner)

2/22/80 Salt River looking north at about 71st Avenue.



2/22/80 Salt River looking upstream from 75th Avenue.



2/22/80 Salt River looking upstream at 75th Avenue and Southern Avenue.



2/22/80 Salt River looking upstream from 75th Avenue.

2/22/80 Salt River - 75th Avenue & Southern (looking upstream)
Note: Erosion along bank. Elevated residence on right side of photo was surrounded by water during peak flows.



2/22/80 Salt River looking northwesterly at approximately 99th Avenue.

2/22/80 Salt River looking downstream vicinity of
99th to 107th Avenues.



2/22/80 Salt River northwesterly at approximately 107th Avenue.

2/22/80 Salt River looking northwesterly at approximately 107th Avenue.

2/22/80 Salt River looking north at 107th Avenue.

2/17/80 Gila River - Gillespie Dam & Old U.S. 80 Bridge.

2/17/80 Gila River - Gillespie Dam & Old U.S. 80 Bridge.



2/17/80 Indian Bend Wash Greenbelt in foreground with Salt River in background.